<u></u>												
Work Orde Thursday, Octobe		i										Page
Item ID: Revision ID:	K642-511			Accept					Setup	Start		
Item Name:	saddle kit 642	-511								Stop		
•	10/28/2010	Start Qty: 4.00			Cust Item I	D:					1 18811181 81	
Required Date: Reference:	11/12/2010	Req'd Qty: 4.00			Customer:							
Approvals:	Process Pla	n:	Date: 10-10-4	Tooling:	Da	ate:		J		Start		
	QC:	"(Date:	_ SPC (Y/N):	Da	ate:				Stop		
Sequence ID/ Work Center ID)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr										
DSI 9467 IIN D206-642	Rev											
100	Rev	N		0.00					······································			
	·	DOCUMENT CONT	ROL							10-1	0-28	/
DC	1	Memo		0.00					1	, ·	7	$\overline{\mathcal{D}}$
Document Control		Create W	hite labels per PPP K642-51	1 CHG004	•						C	Į)

110

Packaging

Packaging

Pick Kit

0.00

A.

Memo

0.00

(1)/1/25 (4)

W/O:	<u> </u>	WORK ORDER CH	WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
						, f					
Part No):	PAR #: Fault Category:	NCR : Yes	No DQ	4 :	_ Date: _					

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section E	Varification							
DATE STE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspecto				
					:2.							
						,						
						ļ.						
								Į.				
			ł.				}					

Work Order ID 63387

Thursday, October 28, 2010 10:51:06 AM



Page 2

Item ID: K642-511 Accept Setup Start **Revision ID:** Stop Item Name: saddle kit 642-511 Start Qty: 4.00 Start Date: 10/28/2010 **Cust Item 1D:** Req'd Qty: 4.00 **Required Date:** 11/12/2010 **Customer:** Reference: Start Run Process Plan: Date:_____ **Tooling:** Approvals: Date: Stop Date: _____ QC: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. **Work Center ID** Description Qty Qty **Run Hours** Code Number Stamp QC4-100% Inspect kits for completeness 0.00 0.00 Memo Quality Control 130 0.00 Packaging Packaging 0.00 Memo Packaging Identify and pack for shipping as per PPP K642-511 140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10-12-09

W/O:		WORK ORDER CHANGES					ν .
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #: Fault Category: NO	CR: Yes	No DQ	٨:	Date: _	

NCR:	WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section E		- Verification Section C	Approval Chief Eng	T
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date			Approval QC Inspector
•							į	
· ·								
						*		
					ļ			

.. Picklist Print

Thursday, October 28, 2010 10:51:12 AM

Work Order ID: 63387

Parent Item: K642-511

Parent Item Name: saddle kit 642-511



Start Date: 10/28/2010

Required Date: 11/12/2010

Start Qty: 4.00

Required Qty: 4.00

Comments:

IPP Rev:A□07.06.05 new issue□EC□ IDD Day D 09 02 05 Day ECNIOSOD LL

	Rev.B 08.02.05	, Per ECN1080	PLL										
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN3C35A BOLT		Purchased	No		,	110	Each	68.0000	3	12 ~ M/	160F2	کیرد_	
	-			Location		Loc	<u>Qty</u>	Loc Code					
				ST353			68						
					109323		6			-			
	1				111724		1		_			2	
	ļ			_	112489		31		<u>نــ</u>	M/1 27	59 10	<i>X</i> 0	
	1				114523		30		<u> </u>		_	1	
AN3C36A BOLT		Purchased	No			110	Each	115.0000		36 ~ M1/6	252/	// C	D 1)4/3
	İ												

1.1	AN3C36A	
My		

Location	Loc Oty	Loc Code
ST353	115	
109771	10	
115358	15	
115518	40	
115882	50	

m/15882 726

Dait Ac	ospace	Ltd								1 1
W/O:				WORK ORDER	CHANGES					e si
DATE	STEP		PRC	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
·										u
Part No	:	F	PAR #:	Fault Category:	NCR:	Yes I	No DQ	\ :	_ Date: _	
	Re	esolution:		Disposition:	QA: N	/C Clo	osed:		Date:	

NCR:									
		Description of NC		Corrective Action Section B		Verification	Ammunud	Ammerical	
DATE STEP		Section A ,	Initial Action Description Sign & Chief Eng Chief Eng Date		Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector	
						,			

Thursday, October 28, 2010 10:51:12 AM

Work Order ID: 63387

Parent Item:

AN4C6A

Bolt

K642-511

Parent Item Name: saddle kit 642-511



Start Date: 10/28/2010

Required Date: 11/12/2010

Start Qty: 4.00

Required Qty: 4.00

N3C41A	
OLT	

Р	'uı	rc.	ha	as

Purchased

No

No

110

Each

111.0000



32 "

Location	Lo	c Oty	Loc Code
FG		4	
103324		4	
ST354		107	
108084		7	
108409		8	
112879		1	
114443		59	
115316		32	
	110	Each	535.0000

Locatio	<u>n</u>	Loc Qty	Loc Code
FG		4	
	103344	4	
ST		4	
	103344	0	
	111295	4	
ST356		527	
	113121	127	
	115016	200	
	116003	200	

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									·		
Part No:		PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	Date: _			
	Reso	olution:	Disposition	ı:	QA: N/C (Closed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORM	IANCE (NC	R)					
DATE	STEP	Description of NC		ction B	Verifi	cation	Approval	Approval			
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sec	tion C	Chief Eng	QC Inspector		
								[:		
								1			

50

114615

Dart Ae	rospace Lt	d							
W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PR	OCEDURE CHANGE By			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Dowt Mark		DAD #							
Part No: PAR #: Resolution:									
		Disposition	:	QA: N/C CI	osed:		Date: _	——————————————————————————————————————	
NCR:				R NON-CONFORMAN	ICE (NCF	()			
DATE	STEP	Description of NC Section A	Corrective Action Section B Initial Action Description			Sign & Verification Section C			Approval QC Inspector
		COSCIONA	Chief Eng	Chief Eng	Date	Jecon		Chief Eng	QO IIISPOOIO
					ŀ				
							. .		
	1		T			_ i		1	

Thursday, October 28, 2010 10:51:12 AM

Work Order ID: 63387

Parent Item:

K642-511

Parent Item Name: saddle kit 642-511



Location

18918


107013 107463

111808

113164

FG

ST340





Purchased

Purchased

Purchased

No

No

No

110

Each

81.0000

Loc Code

Loc Code

104.0000



Start Date: 10/28/2010

Required Qty: 4.00

Required Date: 11/12/2010

Location Loc Qty ST339 81 111819 81 110 Each

90.0000

Loc Qty

86

2

33

50

Each

110



Location Loc Qty Loc Code FG 2 18918 2 ST340 102 107289 110342 2 111648 38 112454 60

/b/4/30

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	, D	ate Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							,		*		
							,				
							į				
Part No:		PAR #:	Fault Cat	egory:	NCR: Y	es No	DQA:	Date: _			
Resolution:			Dispositi	on:	QA: N/0	Close	ed:	Date: _			
NCR:		V	VORK OR	DER NON-CONFORI	MANCE (N	CR)					
DATE	STEP	Description of NC		ection B	Verification			Approval			
DAIL	OILI	Section A	Initial Chief Eng	Action Descriptio Chief Eng	n Si	gn & ate	Section C	Approval Chief Eng	QC Inspector		
									*		
									į		
					İ						

∹G		44	
	104925	44	
ST346		120	
	106785	10	
	107008	10	
	112612	3	
	112794	29	
	112828	27	
	69220	41	

V/O:			V	ORK ORDER CH	IANGES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC inspector
Part No	:	PAR #:	Fault Ca	tegory:	NCF	R: Yes	No DQ	A:	Date: _	
	Reso	lution:	Disposition: 0			QA: N/C Closed: Date				
NCR:		,	WORK OR	DER NON-CONF	ORMANCE	(NCR)			
DATE	0.750	Description of NC	Corrective Action Section			Section B			Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Descr Chief Eng		Sign & Date		cation ion C	Chief Eng	QC Inspecto
								-		

Picklist Print Thursday, October 28, 2010 10:51:12 AM							<u> </u>	Page 6
Work Order ID: 63387 Parent Item: K642-511 Parent Item Name: saddle kit 642-511	14 6 1 1 1 1 1 1 1 1 1	HAT HATT TOOLSAN Bib 1101 1101 1111 1111 1111 1111 1111 1				Date: 10/28/2010	-	Date: 11/12/2010
NAS1149C0532 Purchased	No		110	Each	Start 22.0000	t Qty: 4.00 8 32	Required	d Qty: 4.00
						11 M113	53/	<u>(</u>
	<u>Loc</u> ST:	cation	<u>Lo</u>	c Oty 22	Loc Code			
	51.	103344 109545 111916		8 8 6			- -	
D206-648-013 Manufacture GHW Modification	d No		110	Each	10.0000	4-63,	- 860	
	Loc	cation	<u>Lo</u>	e Qty	Loc Code			
	FG			10				
		42315		1			_	
		47600 62644		1 8			_	
D2652 Manufacture Bushing	d No	02044	110	Each	151.0000	64 6 35	991 <u>(</u>	[[[]] [] (]
,	Lo	cation	Lo	c Oty	Loc Code			,
	FG			44				
1		31985		44				
<u> </u>	STO)20		107			_	
		61645		1			_	
		63650		106				

W/O:	WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·
Part No: PAR #:		PAR #:	Fault Categ	ory:	NCR: Ye	s No I	DQA:	Date: _	
		Disposition	:	_ QA: N/C	Closed:		Date: _		
NCR:			WORK ORDE	R NON-CONFORMA	NCE (N	CR)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	Sig	n& و	rification Section C	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng	Da	ite			a a mapasia
	1		i I		Ī				
							,	·	
							,		

Thursday, October 28, 2010 10:51:12 AM

Work Order ID: 63387

Parent Item:

K642-511

Parent Item Name: saddle kit 642-511



Manufactured

Manufactured

No

No

110

Each

413.0000

Loc Code

4.0000

Start Date: 10/28/2010 Start Qty: 4.00


Required Date: 11/12/2010


Required Qty: 4.00

Saddle LH Out, 206



		Location		Lo	e Qty
		FG			50
			29962		50
		ST022			363
			61331		363
Manufactured	No			110	Each
		Locatio	.n	Lo	c Qty
		ST421	<u></u>	100	.
		31421			4





	 _	- ري			
<u>ode</u>					
	_				
	-			_	
	-			_	

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		•							
Part No	,•	PAR #· Fault Category:	NCR: Yes	No DO	Δ.	Date:	1		

Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C					
		•									
						,					
						*					

Pi	۸k	lic	. 4	$\mathbf{p}_{\mathbf{i}}$	ri:	n t
	CK	8113	i I		r 1	

Thursday, October 28, 2010 10:51:12 AM

Required Date: 11/12/2010

Required Qty: 4.00

Page 8

Work Order ID: 63387

Parent Item:

K642-511

Parent Item Name: saddle kit 642-511



Location

31929

59641

59642

62690

FG

ST031

Location

ST028

Saddle LH Out, 206

Manufactured

Manufactured

Manufactured

No

No

110

110

110

Each

6

14 14

51

6

45

Each

Each

Loc Qty

Loc Qty

20.0000

Loc Code

51.0000

Loc Code

5.0000

Start Date: 10/28/2010 Start Oty: 4.00

6 3559

Location Loc Qty Loc Code ST421 44554 62695 3 ST428A 60905

Dart Ae	rospace	Ltd							
W/O:			WO	RK ORDER CHANGES					• • •
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								l	
Part No	:	PAR #:	Fault Categ	jory: N	CR: Yes	No DQ	A:	_ Date: _	
	Re	esolution:	Disposition: Q			QA: N/C Closed: Date:			
NCR:			WORK ORDE	R NON-CONFORMANO	CE (NCF	R)			
		Description of NC		Corrective Action Section B		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	& Secti	on C	Chief Eng	QC Inspector

Picklist Print Thursday, October 28, 2010 10:51:12	AM				Page 9
Work Order ID: 63387 Parent Item: K642-511 Parent Item Name: saddle kit 642-511				Start Date: 10/28/2010 Start Qty: 4.00	Required Date: 11/12/2010 Required Qty: 4.00
D2939-1 Saddle LH In, 206	Manufactured	No	110 Each	4.0000	
D3396-3 } Spacer	Manufactured	Location ST421 43188 62628 ST428A 58534 No	Loc Qty 3 1 2 1 1 110 Each	31.0000 2 8 V 6 3 9	57 6p G
Spacer		Location FG 26772 ST055 36336 45667 58680	Loc Oty 10 10 21 2 2 17	Loc Code	
D3407-043 Tow Ring	Manufactured	No <u>Location</u>	110 Each <u>Loc Qtv</u>	15.0000 1 4 B B B	1/



W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector
								Prod Mgr	Q moposter
		<u>.</u>							
·							<u> </u>		
Part No:		PAR #:	Fault Categ	_ NCR: Yes N	Date:				
Resolution:			Disposition	:	_ QA: N/C Clo	sed:		Date:	
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NCR))			
DATE	STEP	Description of NC	Corrective Action Section B			Veritics		Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
									÷

Required Date: 11/12/2010

Required Qty: 4.00

Thursday, October 28, 2010 10:51:12 AM

Work Order ID: 63387

Parent Item:

K642-511

Parent Item Name: saddle kit 642-511





Washer







Manufactured

Manufactured

Manufactured

Each

3.0000



Start Date: 10/28/2010

Location Loc Qty Loc Code ST058 54692 3

110

Manufactured No

No

No

Location


42329

52505

ST077

110 Each

13.0000



62691

Location Loc Qty Loc Code FG 10 32409 10 ST059 45913 52981 2 110 Each 847.0000

Loc Qty

847

150

697

Each

Loc Code 559.0000

Location Loc Oty Loc Code ST077 559 47023 16 55500 32 57704 511

110

OSPACE L	iu					•		• •	
		WO	RK ORDER CHANG	SES	-		· · · · · · · · · · · · · · · · · · ·	• .	
STEP	PR	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	PAR #:	Fault Categ	jory:	NCR: Yes	No DC)A:	Date: _		
Resolution:		Disposition	:	QA: N/C Closed: Da				te:	
		WORK ORDE	R NON-CONFORM	ANCE (NC	R)				
	Description of NC	Corrective Action		tion B	Vorif	iootion	Annewal	A	
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec		Chief Eng	Approval QC Inspector	
					,				
	STEP	:PAR #: Resolution: STEP Description of NC	STEP PROCEDURE CHAN PAR #: Fault Category Resolution: Disposition WORK ORDE STEP Description of NC Section A Initial	WORK ORDER CHANGE PROCEDURE CHANGE PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORM STEP Description of NC Section A Se	WORK ORDER CHANGES STEP PROCEDURE CHANGE By PAR #: Fault Category: NCR: Yes Resolution: Disposition: QA: N/C C WORK ORDER NON-CONFORMANCE (NC STEP Description of NC Section A Section B Initial Action Description Sign	STEP PROCEDURE CHANGE By Date	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Approval Chief Eng / Proof Mgr	

114784

115936

244

300

300

Dart	Aer	ospa	ce L	td
------	-----	------	------	----

Dart Ae	rospace Ltd							•
W/O:			WORK ORDER CHANGES					
DATE	STEP	PR	PROCEDURE CHANGE		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Category:	NCR: Ye	s No DQ	A :	Date: _	
	Resolut	ion:	Disposition:	QA: N/C	Closed:		Date: _	
			WORK OPDED NON-COM	IEODMANCE (NO	יםי			

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section E	3	Verification	Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C					
					·						
						,					
				-							
						į					

Thursday, October 28, 2010 10:51:12 AM

Work Order ID: 63387

K642-511

Parent Item Name: saddle kit 642-511

Parent Item:

_MS21043-5



Start Date: 10/28/2010

16 V

Required Date: 11/12/2010

Required Qty: 4.00

Start-Oty: 4.00



Purchased No 110

580.0000 Each

0/4//29 (4)

<u>Location</u>	Loc Qty	Loc Code	
ST301	580		
111819	80		M11/8/9
112314	500		

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
			Ī								
·							· ·				
5											

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
DATE		Description of NC		Corrective Action Section B	Verification	Ammassal	A					
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector				
					·							
			·									
						,						
<u> </u>												

32.17 206L/L-1/L-3/L-4/407 High Gear Float Skidtubes (Tri-Bag Compatible) Parts List -

Item	Qty -511	Qty -512	Qty -541	Qty -547	Qty -013	Part Number	Description
	Х					D206-642-511	SKIDTUBE INSTALLATION, LH
		X				D206-642-512	SKIDTUBE INSTALLATION, RH
	1		x			_D206-642-541	SKIDTUBE 3
				X		D206-642-547	WEARSHOE KIT (REPLACES -543 KIT)
	1	1			X	D206-648-013	GROUND HANDLING KIT
1			1			D3274-041	SKIDTUBE ASSEMBLY
3			1			D2646	* AFT CAP (1)
4			2			AN3C4A	* BOLT (1)
5A			2			AN960C10L	* WASHER (1)
5B			27			D3672-1	* WASHER (REPLACES NAS1515H3L) (1)
6	1			20 .		D2932-1	SADDLE, FWD OUT, LH
-6		1		SAL	 	D2932-1	SADDLE, FWD OUT, RH
7	1			CA	 	D2933-1	SADDLE, FWD IN, LH
7		1			2	D2933-2	SADDLE, FWD IN, RH
8	1	'		<u>Y</u>	111/2	D2938-1	SADDLE, AFT OUT, LH
8	<u>'</u>	1			1.10	D2938-2	SADDLE, AFT OUT, RH
9	1		<u> </u>	1	1 4 1 2 2	D2939-1	SADDLE, AFT IN, LH
9	'	1		1111	 //	D2939-2	SADDLE, AFT IN, RH
10	8	8		11/1/1	*/	AN3C41A	BOLT
11	16	16		7 6	/ 	D2652	BUSHING
12A	8	8		-t	 	MS21043-3	NUT
12B	16	16				D3672-7	WASHER (REPLACES NAS1515H5)
13	4	4				ANSC11A (OR ANSC12A)	* BOLT (2)
14	4	4				AN5C11A (OR AN5C13A)	* BOLT (2)
15A	8	8				AN960C516L	WASHER
15B	8	8				D3672-7	WASHER (REPLACES NAS1515H5L)
16	12	12				AN4C6A	BOLT
17A	24	24				D3672-3	WASHER (REPLACES NAS1515H4L)
17B	24	24				AN960C416L	WASHER
18	12	12				MS21043-4	NUT
20A			9	9		D3537-1	* WEARPAD (1) (REPLACES D2648-3)
21A			1	1		D3537-3	* WEARPAD (1) (REPLACES D3429-1)
22A			1	1		D3535-15	* WEARSHOE (1) (REPLACES D2656-15)
22B			1	1		D3536-15	* GASKET (1)
	 		1			D3535-23	* WEARSHOE (1) (REPLACES D2656-23)
23A	ļ			1	ļ		
23B			1	1		D3536-23	* GASKET (1)
24A			1	1		D3535-39	* WEARSHOE (1) (REPLACES D3287-1)
24B	l		1	1		D3536-39	* GASKET ⁽¹⁾
25A	[]		1	1		D3535-35	* WEARSHOE (1) (REPLACES D2656-35)
25B			1	1		D3536-35	* GASKET (1)
26A		-	78	78		AN3C4A	* BOLT (1)
26B	 		78	78		AN960C10L	* WASHER (1)
26C			78			ALS7-1032-130	* INSERT ⁽¹⁾ (or AK\$4-1032-130, AL\$4-1032-130, AEL\$-1032-130)
30	1	1				D3407-043	TOW RING
32A	1	1	 		 	D3456-1	WASHER
32B	2	2	 			D3457-1	WASHER
33	1	11				MS21043-4	NUT
34			1	-	-	AN4C5A	BOLT
35	 		1		 	AN960C416	WASHER
36			1			D3413-1	RING
- 55			 				
37	10	10			I	D2712	SET SCREW
38	2	2				D2934	SADDLE SPACER
39	2	2				D2935	SADDLE SPACER

continued on next page...

• COPYRIGHT © 2007 BY DART AEROSPACE USA, INC. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Page 39 of 43

continued from previous page...

ITEM	QTY -511	QTY -512	QTY -541	QTY -547	QTY -013	PART NUMBER	DESCRIPTION
40					2	D3414-041	LUG ASSEMBLY (GHW)
41		L			4	AN3C37A	BOLT
—42 —			l — . — .		8	D2652	BUSHING
43					4	MS21043-3	NUT
44					4	AN960C10	WASHER
50	9	9		 		AN3C36A	BOLT
51	3	3				AN3C35A	BOLT
52	24	24				AN960C10L	WASHER
53	24	24				D3672-1	WASHER (REPLACES NAS1515H3L)
54	12	12				MS21043-3	NUT
55	. 2	2				D3396-3	SPACER
56A	1	1				AN5C35A	BOLT
56B	1	1				AN5C15A	BOLT
60	2	2				AN5C32A	BOLT
61	2	2	l	i		AN5C34A	BOLT
62	4	4	1			MS21043-5	NUT

NOTES: (1) DENOTES THAT PART IS INCLUDED WITH D3274-041 ASSEMBLY ABOVE

⁽²⁾ CHOICE OF BOLT WILL DEPEND ON CROSSTUBE (SEE INSTALLATION PROCEDURE)